Subject

For Singapore Ships, MPA Instruction to prevent PSC detention



No. TEC-0897 Date 14 March 2012

To whom it may concern

Please note that, on 15 February 2012, Maritime and Port Authority of Singapore (MPA) issued Preventive action against PSC ship detention at a foreign port and especially at Australian ports as per the message from MPA with Ref. No.FSC5.02. Please see the attachment for details. MPA's main requirements are as follows:

- 1. For all the Singaporean ships under your management, execution of Thorough Inspection (including ISM matters) by Company's shore personnel or Ship's senior officers and rectification of deficiency/ non conformity.
  - In case where any serious deficiency/ non-conformity which can not be rectified immediately is found, reporting to MPA, ClassNK and PSC at calling port,
- 2. Prior to the entry into Australian port, submission of Master's Declaration to MPA, on completion of thorough inspection and no serious deficiency/ non conformity which is not rectified or reported.

(Contact address: MPA: shipping@mpa.gov.sg ClassNK: Departments shown below)

In order to make thorough inspections requested by MPA more effectively, please refer to the attached lists of "Major Reasons of Detention at Australian Ports in 2011" basing on ClassNK database of PSC. For PSC Information updated monthly, please visit to the Society's web-site information on the deficiencies pointed out at PSC Inspections.

 $http://www.classnk.or.jp/ > Products \ \& \ Services > Statutory \ Services > Safety \ Management \ Systems \ (ISM) > Monthly \ PSC \ Information$ 

For any questions about the above, please contact:

[Survey]

NIPPON KAIJI KYOKAI (ClassNK)

Survey Department, Administration Center, Head Office

Address: 4-7 Kioi-cho, Chiyoda-ku, Tokyo 102-8567, Japan

Tel.: +81-3-5226-2027 / 2028

Fax: +81-3-5226-2029 E-mail: svd@classnk.or.jp

(To be continued)

### NOTES:

- ClassNK Technical Information is provided only for the purpose of supplying current information to its readers.
- ClassNK, its officers, employees and agents or sub-contractors do not warrant the accuracy of the information contained herein and are not liable for any loss, damage or expense sustained whatsoever by any person caused by use of or reliance on this information.
- Back numbers are available on ClassNK Internet Homepage (URL: www.classnk.or.jp).

# [Audit]

Safety Management Systems Department, Administration Center, Head Office

Address: 4-7 Kioi-cho, Chiyoda-ku, Tokyo 102-8567, Japan

Tel.: +81-3-5226-2173 Fax: +81-3-5226-2174 E-mail: smd@classnk.or.jp

## Attachment:

1. Message from MPA Ref. No. FSC5.02 (dated 15 February 2012)

2. Major Reasons of Detention at Australian Ports in 2011

Attachment 1. to ClassNK Technical Information No.TEC-0897

Our ref: FSC 5.02

Dear Sir / Madam

The MPA is committed to maintain a quality fleet in the Singapore Ship Registry. To this end, we have been engaging our shipowners and companies, including our authorised classification societies (ROs), through various forums, regular meetings and dialogue sessions to urge them to maintain and operate their vessels safely at all times. We have constantly promoted the continual improvement of company's safety management systems to achieve better safety performance. We have also been sharing relevant information on all ship detentions in the Singapore Ship Registry in order to make our companies and ROs aware of the common deficiencies that caused ship detentions (i.e. ships that are operating at higher/unacceptable risk levels) so that they can implement necessary measures to avoid similar problems for their fleet.

In this respect, please be informed that we are currently experiencing high rate of port State control (PSC) detention in the months of January and February, and in particular in Australian ports. Seven out of 12 PSC detentions have taken place there. Please see attached list of PSC detentions and table of detention deficiencies below this email to understand the problem. You will notice that these ships are still being detained on grounds of common deficiencies that we have been highlighting to our companies for preventive action before their ships encounter the same problem.

The MPA takes a serious view of any ship detention in the fleet. The current situation is really unacceptable. We are taking firm and deterrent actions to address this undesirable development.

The Director of Marine will not hesitate to take necessary action to verify, monitor and ensure the proper maintenance and operation of Singapore ships and company's safety management systems. These actions may include priority ship boarding by MPA's Flag State Control (FSC) surveyors to carry out expanded inspections and audits, imposing additional and unscheduled surveys and/or audits on ships and their companies at intervals deemed necessary to achieve the desired results.

Your company is hereby requested to take the following actions:

- 1. Urgently disseminate this information to key personnel in your office and onboard your ships;
- 2. Arrange for your vessels to be thoroughly inspected by shore personnel or senior ship's officers to ensure the vessel, its equipment and system, and the crew are in good order, and to deal with any deficiencies or non-conformances in accordance with the provisions of the ISM Code. Serious deficiencies on the vessel which cannot be rectified immediately shall be reported to your company, MPA (<a href="mailto:shipping@mpa.gov.sg">shipping@mpa.gov.sg</a>) and/or the ROs which issued the ship's certificates, as well as the competent authority of the port State if the vessel is calling at a foreign port.
- 3. If your company has any Singapore ships calling at Australian port(s), submit a declaration from the ship's master to MPA by email that action as required in item No.2 has been carried out on his/her vessel and that there is no serious deficiencies which have not been properly dealt with, or which have not been reported to the appropriate authorities, prior to calling at the first Australian port. Failure to comply with this instruction will be taken seriously.

We seek your kind understanding and urgent attention on the matter. We hope that with your company's cooperation and efforts to achieve our mutual objectives, there will be no need for MPA to take exceptional measures. Dialogue sessions are being organised to follow up with our companies and ROs.

For sake of good order, your company is requested to acknowledge receipt of this email to my colleague, Mr Ng Tian Ann (<u>Tian\_Ann\_NG@mpa.gov.sg</u>). Any query relating to this email should also be addressed to him.

Thank you.

For Director of Marine

<u>Lim</u> Hock Lye • Assistant Director (Flag State Control) • Maritime and Port Authority of Singapore (MPA) • DID: (65) 6375 6219 • Fax: (65) 6375 6231 • www.mpa.gov.sg

Our Vision • A leading maritime agency driving Singapore's global maritime aspirations

**Our Mission** • To develop and promote Singapore as a premier global hub port and an international maritime centre, and to advance and safeguard Singapore's strategic maritime interests

PS: When you are sending emails to the Flag State Control Department, please direct them to our common email address: <a href="mailto:shipping@mpa.gov.sg">shipping@mpa.gov.sg</a>. Thank you

#### **Detention deficiency**

- 0117 Safety Management Certificate (SMC/ISM Code) Interim SMC issued in October 2011 and valid till April 2012 due to change of company. Internal audit not performed within 3 months. Internal audit planned for this vessel in July 2012.
- 0221 Certificates for master and officers Second Engineer holding COC of III/3, not III/2 as required, as per Minimum Safe Manning Document issued to vessel by the Flag State.
- 0230 Manning specified by minimum safe manning document Vessel's manning not as specified by minimum safe manning certificates insufficient GP and IR ratings.
- 0615 Rescue boats Rescue boat launching arrangements defective.
- 0739 Emergency Fire Pump Unable to pressurise the fire main.
- 0743 Fire-dampers Port and starboard engine room fire dampers defective.

  Fire-dampers Engine room fire dampers defective
- 0936 Steering gear No. 2 Steering gear motor out of operation.
- 0938 Damage to hull due to weather or ship operation Bulbous bow damaged due to collision during mooring.
- 1430 Auxiliary engine Emergency generator does not start or connect automatically to emergency switchboard on failure of the main supply.
- 1550 Lights, shapes, sound-signals Horizontal arc of visibility for stern light not as per regulation.
- 1623 MF/HF radio installation MF/HF DSC test failed.
- 1745 15 PPM alarm arrangements 15 ppm alarm for oily water separator not working.
- 2043 Monitoring of voyage or passage plan Monitoring of passage plan not adequate to prevent vessel running aground (pilot on board).
- 2530 Resources and personnel Deficiency No.1, 2 and 3 are objective evidence that the vessel's SMS does not ensure the vessel is manned as required by the safe manning certificates.
- 2535 Development of plans for shipboard operations Safety Management System fails to ensure that hours of work/rest records are recorded accurately. Master is unable to ensure that the officers are sufficiently rested.
- 2535 Development of plans for shipboard operations SMS fails to ensure watchkeeping rest hours are recorded correctly. Master unable to ensure watchkeepers are rested as per STCW requirements.
- 2535 Development of plans for shipboard operations As evidenced by deficiency No.1 and No.2, the vessel's SMS does not provide for adequate development of plans for shipboard operations.
- 2535 Development of plans for shipboard operations Vessel's SMS does not ensure appropriate charts are used for the voyage, as evidenced by deficiency No.1.

# **Major Reasons of Detention at Australian Port in 2011**

Term: 1 January- 31 December 2011

Nos. of detention	Deficiency Code	Keyword	Details (number of finding)
27	11101	Lifeboat Arrangements	- On-load releasing gear defective/ inoperable (20)
	11129		- Steering system defective (3)
			- Engine & Its Starting System (2)
			- Crew's insufficient familiarization with the operation (2)
11	07114	Fire Dampers	- E/R Fire Damper (at fan or funnel) defective/ inoperable (11)
	07115		
10	05102/105	Radio Installation	- HF/MF defective (5)
	05114		- Reserve power source defective (5)
7	10111	Charts (incl. ECDIS).	- Insufficient charts for intended voyage (Paper x2 + ECDIS x1)
	10112		- Charts not updated (1 + 1)
	10127		- Officer's non familiarization with operation of ECDIS (1)
	10133		- Charts not utilized (1)
7	04102	Emergency Fire Pump	- Emergency Fire Pump defective/ not sufficiently working (7)
	07108/ 113		
7	14104/107/108	Oil & oily mixtures	- Oily water separator/ 3 way valve/ 15ppm alarm inoperable (2)
	14119		- Crew's inadequacy/ non familiarization to the operation (4)
			- Illegal modification of sample line (1)
6	03104	Closing Appliances	- Hatch Cover hinges & locking devices defective (3)
	03105	required by Load Line	- Air Pipe Head defective (2)
	03108		- Air Vent defective (1)
6	14402	Sewage Treatment Plant	- Sewage Treatment Plant defective (6)
3	04103	Emergency Generator	- Emergency Generator defective/ not able to start (3)
	13108		

Nos. of detention	Deficiency Code	Keyword	Details (number of finding)
20	15106	Development of plans for	- SMS fails to ensure that approved navigation chart (10)
		shipboard operations	- SMS fails to ensure watch keeping rest hours are recorded correctly (9)
			- Passage Plan prepared non- Designated shipping Area (1)
11	15104	Maintenance of the ship	- ISM has not ensured maintenance of ship and equipment (6)
		and equipment	- Company SMS is not effective in maintenance of ship & equipment (3)
			- SMS fails to identify equipment the sudden operation failure (1)
			- Maintenance of ship & equipment are not effective (1)
9	15109	Masters responsibility and	- SMS not ensure using large scale chart (7)
		authority	- Master has not ensured watch-keepers are adequately rested (2)