

# Palau International Ship Registry



Europe Head Office Piraeus, 18536, Greece 5, Sachtouri Street 6 <sup>th</sup> floor T: +30 210 4293500 F: +30 210 4293505 <a href="mailto:info@palaureg.com">info@palaureg.com</a>	USA Head Office The Woodlands, TX, 77380 9595 Six Pines Drive, Suite 8210, Office 277 T: +1 832 631 6061 F: +1 832 631 6001 <a href="http://www.palaureg.com">www.palaureg.com</a>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

## MARINE CIRCULAR 130.1

**To: ALL SHIPOWNERS, MANAGERS, MASTERS, DEPUTY REGISTRARS AND RECOGNIZED ORGANIZATIONS**

**Subject: GUIDELINES FOR THE PREVENTION AND RESOLUTION OF STOWAWAYS**

### 1. Reference

- 1.1 IMO Resolution MSC.312(88), *Revised Guidelines on the Prevention of Access by Stowaways and the Allocation of Responsibilities to Seek the Successful Resolution of Stowaway Cases*, adopted December 2<sup>nd</sup> 2010
- 1.2 IMO Resolution FAL.11(37), *Revised Guidelines on the Prevention of Access by Stowaways and the Allocation of Responsibilities to Seek the Successful Resolution of Stowaway Cases*, adopted September 9<sup>th</sup> 2011

### 2. Purpose

- 2.1 The Palau Ship Registry Administrator is to provide guidelines on the prevention of stowaway access to ship and the resolution of such cases on board Palau registered vessels.

### 3. Applicability

- 3.1 These guidelines applies to all vessels registered with the Palau flag to which the International Ship and Port Security Code (ISPS Code) applies, however, this Marine Circular shall be circulated through all Palau registered vessels.

### 4. General Information and requirements

- 4.1 Despite the implementation of the ISPS Code, preventing stowaway access and properly handling stowaways once they have been discovered is challenging.
- 4.2 In accordance with the ISPS Code, procedures for the prevention of stowaways must include those designed to prevent unauthorized access to the ship, therefore, the Ship Security Plan (SSP) must include procedures for conducting searches to aid in preventing stowaways.

### 5. General Guidelines

- 5.1 Stowaways arriving at or entering a coastal State without the required documents are generally considered illegal entrants. Decisions on handling such situations are governed by the States where such arrival or entry occurs.
- 5.2 Stowaways seeking asylum should be treated in accordance with international instruments.
- 5.3 Every effort should be made to avoid situations where stowaways have to be detained aboard a ship indefinitely. In this regard, States should cooperate with



# Palau International Ship Registry



Europe Head Office Piraeus, 18536, Greece 5, Sachtouri Street 6 <sup>th</sup> floor T: +30 210 4293500 F: +30 210 4293505 <a href="mailto:info@palaureg.com">info@palaureg.com</a>	USA Head Office The Woodlands, TX, 77380 9595 Six Pines Drive, Suite 8210, Office 277 T: +1 832 631 6061 F: +1 832 631 6001 <a href="http://www.palaureg.com">www.palaureg.com</a>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

the Company in arranging the disembarkation of stowaway(s) to an appropriate State.

- 5.4 Where the nationality, citizenship, or right of residence cannot be established, the port State of stowaway embarkation are to accept the return of the stowaway for examination, pending final case disposition. However, this may not always be the case.

## 6. Means of Gaining Access to a Vessel

- 6.1 The following are the most common ways for stowaways to board vessels:

- 6.1.1 Climbing up over the side of a vessel, using mooring lines or poles and then hiding in an unlocked locker or void space, an empty drum, a lifeboat, or under containers stowed on deck;
- 6.1.2 Entering soft top containers through the top so that the customs or security seals on the container doors remain intact before the container is loaded on the ship;
- 6.1.3 Hiding in empty containers;
- 6.1.4 Hiding in rudder trunk spaces (especially when ship is in ballast condition);
- 6.1.5 Hiding in ventilation trunks (especially in Ro-Ro Car Carriers);
- 6.1.6 Hiding in the ceiling of the tally office;
- 6.1.7 Disguising themselves as stevedores; and
- 6.1.8 Acts of impropriety and/or malfeasance on the part of the port agent or port facility security officer.

## 7. Preventive Measures for the Company/Master

- 7.1 Companies and Masters should ensure that adequate security arrangements are in place to prevent illegal boarding of the vessel. All stowaway preventive measures should be documented in the SSP.
- 7.2 When calling at ports where there is a risk of stowaway embarkation, security arrangements should contain, at a minimum, the following preventive measures as deemed appropriate and on the evaluation of the risk assessment being implemented:
  - 7.2.1 All doors, hatches and means of access to holds or stores, which are not used during the ship's stay in port should be locked;
  - 7.2.2 Shoreside access points to the ship should be kept to a minimum and be adequately secured;



# Palau International Ship Registry



Europe Head Office Piraeus, 18536, Greece 5, Sachtouri Street 6 <sup>th</sup> floor T: +30 210 4293500 F: +30 210 4293505 <a href="mailto:info@palaureg.com">info@palaureg.com</a>	USA Head Office The Woodlands, TX, 77380 9595 Six Pines Drive, Suite 8210, Office 277 T: +1 832 631 6061 F: +1 832 631 6001 <a href="http://www.palaureg.com">www.palaureg.com</a>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

- 7.2.3 Waterside access areas seaward of the ship should be adequately secured;
- 7.2.4 Adequate deck watch should be kept;
- 7.2.5 All persons coming aboard the vessel should be required to present a valid permit (no permit = no access);
- 7.2.6 If cargo operations require several stevedores, the Stevedore Supervisor should provide the Ship Security Officer (SSO) with a detailed count of the number of stevedores prior to cargo handling and final confirmation once they are all ashore.
- 7.2.7 All embarkations and disembarkations should be strictly tallied by SSO or designated crew member;
- 7.2.8 Adequate means of communication should be maintained; and
- 7.2.9 Adequate night lighting should be maintained both inside and along the hull.
- 7.3 When departing from a port, a ship is required to undergo a thorough search procedure for the prevention of stowaways which should be documented in the SSP with priority given to places where stowaways are most likely to hide. Search methods that could harm secreted stowaways should not be used.
- 7.4 To ensure that no stowaways are present, areas to be fumigated or sealed should be thoroughly searched before proceeding.
- 7.5 Companies should seek advice from their P&I Club regarding stowaways and smuggling. In many cases the P&I Clubs have informative material, suggestions for preventative procedures, and experience in risk assessment for these incidents.

## 8. Risk Management

- 8.1 If a stowaway is found, the vessel may be held responsible for the cost and liabilities of disembarkation and repatriation.
- 8.2 Consider taking the following additional steps to mitigate risk:
  - 8.2.1 Clearly state the responsibility for cargo operations, stevedores and stowaways in the charter party terms;



# Palau International Ship Registry



Europe Head Office Piraeus, 18536, Greece 5, Sachtouri Street 6 <sup>th</sup> floor T: +30 210 4293500 F: +30 210 4293505 <a href="mailto:info@palaureg.com">info@palaureg.com</a>	USA Head Office The Woodlands, TX, 77380 9595 Six Pines Drive, Suite 8210, Office 277 T: +1 832 631 6061 F: +1 832 631 6001 <a href="http://www.palaureg.com">www.palaureg.com</a>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

- 8.2.2 Brief the vessel's officers and crew in advance about specific risks at impending ports of call;
- 8.2.3 Demonstrate ISPS Code compliance, including proper recordation of security drills and exercises in the vessel's log;
- 8.2.4 Seek the latest information about port conditions from local shipping agents;
- 8.2.5 Ensure that the SSO is provided with the means to accurately assess the situation and prepares the vessel accordingly;
- 8.2.6 Plan and discuss vessel access control, in particular gangway checks with the crew in advance;
- 8.2.7 Anticipate and estimate the purpose for and volume of visitors/workers that may come aboard the vessel;
- 8.2.8 Regularly check for the presence of unauthorized persons aboard during time at anchorage and at berth; and
- 8.2.9 Be sure to conduct a search for unauthorized persons prior to departure.

## 9. Reporting Stowaway Incident

- 9.1 Initial notification of a stowaway incident should be submitted via e-mail to the Palau Ship Registry Administrator's Technical Department at [technical@palaureg.com](mailto:technical@palaureg.com) within 24 hours of when the stowaway(s) are discovered on board.
- 9.2 When reporting stowaway cases, see the Revised Guidelines on the Prevention of Access by Stowaways and the Allocation of Responsibilities to Seek the Successful Resolution of Stowaway Cases adopted by the International Maritime Organization (IMO) by Resolutions MSC.312(88) and FAL.11(37) for further guidance.

## 10. Investigation and Review of Stowaway Incidents

- 10.1 The discovery of a stowaway indicates a breach in ship security. As such, stowaway incidents should be reviewed to identify the root cause(s) of the security breach and the actions necessary to prevent reoccurrence, such as amending the SSP and implementing additional security measures.



# Palau International Ship Registry



Europe Head Office Piraeus, 18536, Greece 5, Sachtouri Street 6 <sup>th</sup> floor T: +30 210 4293500 F: +30 210 4293505 <a href="mailto:info@palaureg.com">info@palaureg.com</a>	USA Head Office The Woodlands, TX, 77380 9595 Six Pines Drive, Suite 8210, Office 277 T: +1 832 631 6061 F: +1 832 631 6001 <a href="http://www.palaureg.com">www.palaureg.com</a>
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

## 11. Handling of Stowaway Incidents by Port State Control

11.1 Port State authorities have detained vessels entering port with stowaways for being in violation of the ISPS Code. External audits of the SSP and other actions may be required in order to lift the detention. Some authorities have also imposed requirements that the Company hire private security guards for the duration of the vessel's port call when stowaways are found aboard.

## 12. Contact

12.1 Any inquiries concerning the subject for this Marine Circular should be directed to the Palau Ship Registry Administrator at [technical@palaureg.com](mailto:technical@palaureg.com)

Click [here](#) or use the below QR Code for the list of the last updated Marine Circulars

